

Project:	Alaska Copper \	<u> </u>	Inspection Date: 12/20/19			
Project No.: 19ACW1			Technician: Elaine Lytle			
System Perfo	rmance:					
Was system ru	nning during the i	nspection? 🛛 Yes	□ No			
Flow Rates (gp	m)	Influent 93.4	Effluent	158.7	The flows should be ~155 gpm	
Bag Filter #1 Pr	essures (psi)	Influent 12	Effluent	13	The bag filters should be replaced	
Bag Filter #2 Pr	essures (psi)	Influent 11	Effluent	12	if differential pressure > 8 psi	
Carbon Filter P	ressures (Lead)	Influent 11	Effluent	5	The carbon filters should be	
Carbon Filter P	ressures (Lag)	Influent 4	Effluent	0	backflushed if differential pressure > 8 psi	
Were the bag f	ilters replaced?	⊠ Yes □ No				
Was the carbon	a backflushed?	□ Yes ⊠ No				

Maintenance and Inspection Checklist:

Task	Completed (Y/N)	Issues/Notes/Comments
Walchem Controller Inspected	⊠ Yes □ No	no issues
Flow Meters Inspected	⊠ Yes □ No	reading properly
Level Sensor Cleaning/Inspection	⊠ Yes □ No	reading properly
Inspect System Plumbing	⊠ Yes □ No	no leaks
Pumps Inspected	⊠ Yes □ No	running well
General Housekeeping	⊠ Yes □ No	Used cartridge filters left out near system.
Chemistry Level	⊠ Yes □ No	∼full 55 gallon drum
Safety Materials Inspected	⊠ Yes □ No	in job box
pH Probe Inspection/Calibration	⊠ Yes □ No	pH probe seems to be drifting



			_					
W	יבי	tρ	r S	ar	n	ni	ın	σ.
	•			ч.	••	р,		~:

Were water samples ta	ken!	⊠ Yes	⊔ No		
Raw water:	рН _	5.70	Turbidity	7.30	NTU
Bag Filter Influent	рН _	9.18	Turbidity	13.2	NTU
Bag Filter Effluent	рН _	9.28	Turbidity _	11.6	NTU
Carbon Filter Influent	рН _	8.31	Turbidity	5.50	NTU

Carbon Filter Effluent pH 7.45 Turbidity 4.84 NTU

Monthly Tasks:

Were samples sub	☐ Yes	⊠ No			
Analytical Lab:			_		
Was Walchem dat	☐ Yes	⊠ No			
Were the tank slu	☐ Yes	⊠ No			
Sludge Depth (inches):					
Decant Tank:	N/A				
Treatment tank:	N/A				
Backflush tank:	N/A				
Main lift station:					
North lift station:	N/A				
South lift station:	N/A				

Additional Comments, Recommendations and System Upsets:

When I arrived on site the system was shut off due to the cartridge filters being plugged. Cartridge filters were changed out and 8 were dropped off.

Elaine Lytle	Treatment Tech	12/20/19
Technician	Title	Date

Submit

Page 2 of 2